



Square Groin Vault
 With Transverse and Longitudinal ribs with
 segmental arches
 Quadripartite vaulting
 with equal height ordinates

Radius = 11.31
 Semi Minor Axis = 11.31
 Semi Major Axis = Radius ÷ cos(45°)
 Semi Major Axis = 16

